

## Noise study using pulse generator



## Comments on previous measurements

- The output level of the pulse generator was not constant at all
  - needs very high output (>200 mV) to have 100mV measured height at ~16MHz and ~45MHz
  - this resonance like behavior was removed by replacing the long (16ns?) cables to short (3ns) cables ← according to Marvin, it may be due to non-perfect impedance matching and overlaid waves
- Noise comes from a potential source most of the time, not from a voltage source
- Repeat the measurement with fixed output (100mV), plus short cables

## New result



100

200

300

400

pulse height (mV)

500

Module B is more sensitive

almost linear with offset